



भाकृअनुप-राष्ट्रीय केला अनुसंधान केंद्र
(भारतीय कृषि अनुसंधान परिषद)
थोगमलै रोड थायनूर पोस्ट
तिरुच्चिरापल्लि. - 620 902. तमिलनाडु

ICAR - National Research Centre for Banana
(Indian Council of Agricultural Research)
Thogamalai Road, Thayanur P.O.
Tiruchirapalli - 620 102, Tamil Nadu, India



F.No.9-4(55)/2016-Estt./ 415-421

Date: 24.06.2016

To

Sub : Contract work regarding repair and painting work for the overhead tank at ICAR
- NRCB Research Farm, Tiruchirapalli

Sir/s,

Quotations are invited by the Director, ICAR - NRC for Banana, Tiruchirapalli for undertaking repair and painting work for the overhead tank available at ICAR - NRCB Research Farm, Podhavur, Tiruchirapalli as per the specifications given below.

S. No.	Name of the article	Qty.
1.	Repair and painting work for the overhead water tank available at ICAR - NRCB Research Farm, Podhavur, Tiruchirapalli as per the specification in Annexure - I	1 Job.

NOTE: MATERIALS AND LABOUR REQUIRED FOR UNDERTAKING REPAIR AND PAINTING WORK FOR THE OVERHEAD TANK AT ICAR - NRCB RESEARCH FARM, PODHAVUR, TIRUCHIRAPALLI HAS TO BE PROVIDED BY THE CONTRACTOR. YOUR COMPITATIVE RATE FOR UNDERTAKING ABOVE WORK AS PER THE REQUIREMENT MAY BE QUOTED.

You are requested to quote your competitive rate (s) for undertaking the above work on contract basis. Your quotation addressed to the Director, ICAR - National Research Centre for Banana, Thogamalai Road, Thayanur Post, Tiruchirapalli - 620 102 (T.N.), should reach this office on or before 12.07.2016 (Tuesday) by 12.00 PM in a sealed cover superscribing "Quotation for contract work regarding repair and painting work for the overhead water tank available at ICAR - NRCB Research Farm" - Due 12.07.2016 (Tuesday) by 12.00 PM". Failure to do so would result in rejection of quotation.

Phone : 0431-2618125 | Fax : 0431-2618125

Email : director.nrcb@icar.gov.in | directornrcb@gmail.com

Skype : nrcb.director | website : www.nrcb.res.in



The right to accept or to reject all or any of the quotation in part or full is reserved.

NOTE: You are requested to send your quotations through "SPEED POST" only and not through "COURIER SERVICE".

Yours faithfully,


Assistant Administrative Officer


24/6/2016

Copy to:

1. The Chairman (WLM)
- ✓ 2. The Chairman (PMEC) - for uploading in NRCB website
3. Member Secretary (WLM)
4. The Nodal Officer (CPPP) - for uploading in CPP Portal
5. Pvt. Secy. to Director

Name of work : Repair and painting of Over Head Tank at Farm

DSR item	Description	Qty	Unit
14.67	Finishing walls with Premium Acrylic Smooth exterior paint with Silicone additives of required shade , water proof paint APEX ULTIMA		
14.67.1	Old work (Two or more coats applied @ 1.43 ltr/ 10 sqm) over existing cement paint surface.	1590	sqm
MR	Providing and fixing double scaffolding system on the exterior side, upto seven story height made with 40mm dia. M.S. tube 1.5 m centre to centre horizontal & vertical tubes joining using casino poles scaffolding for working platform etc. and maintaining it in a serviceable condition for the required duration as approved and removing it there after .The scaffolding system shall be stiffened with bracings, runners, connection with the building etc wherever required for inspection of work at required locations with essential safety features for the workmen etc. complete as per directions and approval of Engineer-in-charge .The elevational area of the scaffolding shall be measured for payment purpose .The payment will be made once irrespective of duration of scaffolding, or providing rope ladder scffolding from top to bottom of water tank.	1 JOB	sqm
14.54	Painting with synthetic enamel paint of approved brand and manufacture of required colour to give an even shade :		
14.54.1	One or more coats on old work.For hand rails	120	sqm
14.68	Painting (one or more coats) on CI cast ironpipes, rain water, soil, waste and vent pipes and fittings with black anticorrosive bitumastic paint approved brand and manufacture on old work :		
MR	100 mm diameter pipes	20 m	1 job
MR	150 mm diameter pipes	20m	2 job
MR	mason charges for cement repair works if any small damages in the wall, column , floor etc to complete the work including , cement , sand and other materials required for completing the work		1 job
	Contegencies		



 27/6/2016